


Hillsboro Transit Center Progress Report

January 2022



PROGRESS



Recently completed work:

- Curb and gutter install
- Canopy glazing install
- Storefront glazing install
- Waiting room roofing

Upcoming work:

- Exterior building panels
- Interior finishes
- Bus lane and sidewalk



On-street canopies for bus boarding with glass installed



Transit center waiting room (looking north)